



72: HELVU @PR#1831 10/26/21

PURCHASE REQUEST

Dept./Office: **HELVU**PR #: **GF-2021-10-01287**Date: **10-12-2021**Section/End-User: **Vincent Paul C. Asilom**Category: **Vehicle Supplies**Funding Source: **General Fund - MOOE**Project Title/Code: **Motor Pool Services 2022**

Item #	Item Description	Unit	Qty	Unit Cost	PAR/ICS	Total Cost
1	General Engine repair of Mitsubishi Strada 2003 model, (4D56 engine)	unit	1	75,000.00		75,000.00

Specification:

- 1 set Overhauling gasket
- 4 pcs Piston standard
- 1 set Piston ring standard
- 4 pcs Cylinder liner standard
- 1 set Crankshaft main bearing
- 1 set Conrod bearing
- 1 set Thrust bearing
- 4 pcs intake valve
- 4 pcs Exhaust valve
- 8 pcs Valve guide
- 1 pc Silent shaft, upper bearing
- 1 pc Silent shaft, Lower bearing
- 4 pcs Nozzle tip
- 2 pcs Engine support
- 1 pc Transmission support
- 1 pc Fuel filter assembly
- 1 pc Oil filter
- 1 pc Radiator hose upper
- 1 pc Radiator hose lower
- 1 pc Radiator cap
- 4 ltrs Coolant
- 1 pc Timing belt, jap. 163T
- 1 pc Balancer belt, jap. 99T
- 1 pc Tensioner bearing, timing belt, jap.
- 1 pc Tensioner bearing, balancer belt, jap.
- 1 pc Water pump
- 1 pc Water jacket
- 1 pc Oil sender switch
- 4 ft Fuel hose
- 4 ft Water hose
- 10 pcs Clip, hose
- 4 pcs Glow plug

- 1 pc Belt, alternator 9.5 x 1000
- 1 pc Belt, power steering, 4PK1120
- 1 pc Belt, Aircon, 13 x 785
- 1 pc Balancer shaft sleeve (small)
- 1 pc Balancer shaft sleeve (big)
- 8 pcs Valve set
- Machining cylinder head/block
- Calibration injection pump

2	General Engine repair of Rosa Bus 01 (4D35 engine)	unit	1	120,000.00		120,000.00
---	---	------	---	------------	--	------------

Specification:

- 1 set Overhauling gasket
- 4 pcs Piston standard
- 1 set Piston ring standard
- 4 pcs Cylinder liner
- 1 set Main bearing standard
- 1 set Con-rod bearing standard
- 4 pcs Piston pin bushing
- 1 set Camshaft bushing standard
- 1 set Thrust bearing standard
- 1 set Intake/ Exhaust valve
- 1 set Valve guide
- 1 pcs Water pump assembly
- 2 pcs Engine support
- 4 pcs Glow plug
- 1 pc Oil sender switch
- 1 pc Clutch pressure
- 1 pc Clutch Disc
- 1 pc Release bearing
- 1 pc Pilot bearing
- 1 pc Crank shaft pulley
- 1 pc Oil filter
- 1 pc Fuel Filter
- 1 pc Alternator belt
- 1 pc Radiator hose upper
- 1 pc Radiator hose lower
- 5 ltrs Coolant
- 1 pc Radiator cup
- 2 tube Three bond
- 2 tube Pioneer silicon red
- 3 pcs PLastigage (for diesel engine)
- Machining of cylinder Head/Block
- Calibration Injection pump and replace nozzle tip






3	General Under Chassis Repair of Mitsubishi Rosa Bus 01	unit	1	40,000.00		40,000.00
---	---	------	---	-----------	--	-----------

Specification:

- 1 set King Pin
- 24 pcs Leaf spring bushing
- 1 pcs Draglink
- 2 pcs Tie rod end
- 2 pcs Stabilizer bar bushing
- 2 pcs Stabilizer link
- 3 pcs Cross bearing
- 1 pc Center bearing
- 2 pcs Brake drum front
- 2 pcs brake drum rear
- 2 pcs Wheel hub bearing front inner (30207)
- 2 pcs Wheel hub bearing front outer (30210)
- 4 pcs Wheel hub bearing rear inner/outer

	TOTAL					235,000.00
--	--------------	--	--	--	--	-------------------

Purpose: For repair & maintenance

Checked by:		Funds Available:	
 MARLON G. BURLAS		 ALICIA M. FLORES	
TWG - Vehicle Supplies		HEAD, BUDGET OFFICE <i>gm</i> <i>Rm-MV</i>	
Signature:	Requested by:	Noted by:	Approved by:
	 VINCENT PAUL C. ASILOM	 MARLON G. BURLAS	 EDGARDO E. TULIN
Designation:	END USER	UNIT HEAD, PROJECT LEADER	PRESIDENT, VSU