PPMP #: 176-5-89-2021-7-0-44



Republic of the Philippines **VISAYAS STATE UNIVERSITY**

Visca, Baybay City, Leyte



PURCHASE REQUEST

PR #: GF-2021-09-00737

Date: 09-02-2021

Dept./Office: ODPP

Category: Construction and Electrical Supplies

Section/End-User: Mario C. Bantugan

Project Title/Code: Repair of Ceiling CME 2 Storey

Building

Funding Source: General Fund - MOOE

Item #	Item Description	Unit	Qty	Unit Cost	PAR/ICS	Total Cost
	Labor Services, Repair of Ceiling, CME Building	lot	1	135,000.00		135,000.00

Specification:

- 1. Repair of Exterior Ceiling
- 2. Removal of Damaged Ceiling Frames and Boards
- 3. Hauling of Construction Materials
- 4. Removal and Installation of Scaffoldings
- 5. Installation of Metal Ceiling Frames and Cement Boards
- 6. Painting of Ceiling
- 7. Application of Putty (Skim coat)
- 8. Application of 2 Coats Paint

	TOTAL			135,000.00						
Purpose: For use in CME Building										
Checked by:	MARLON G. BURLAS			S. PANCITO AND						
TV	VG - Construction and Electrical S	upplies	HEAD, BUDGET OFFICE CM-SD BMC							
	Requested by:	Noted by:		Approved by:						
Signature: Printed Name:	MARIO C. BANTUGAN	MARIO LIL	O P. VALENZONA	EDGARDO E. TULIN						
Designation:	END USER	UNIT HEAD,	PROJECT LEADER	PRESIDENT, VSU						