

## OFFICE OF THE DIRECTOR FOR PHYSICAL PLANT

Visca, Baybay City, Leyte, PHILIPPINES Telefax: 1041(LOCAL) Email: www.ppo.@vsu.edu.ph Website: www.vsu.edu.ph

## REPAIR AND MAINTENANCE REQUEST

Filled in by requesting party		Filled in by PPO	
Date filed : December 9, 2021		Date received	
Apartment No./ Sc Department	ent of Animal ience	Received by  Designation/	Name & Signature
Maintenance		control number	: (1) for maintenance team
ii. One (1) job request in e iii. Job request control nun	every of PPO unit		(1) is manuscript to the
Please check and specify the nature of v	work requested		
<ul> <li>□ Vehicle Repair</li> <li>□ Welding Works</li> <li>□ Machining works</li> <li>□ Instrumentation equipment &amp; Laboratory instrument</li> </ul>		<ul> <li>□ Electrical Works</li> <li>□ Heating, Ventilating, Air conditioning &amp; Refrigeration</li> <li>□ Others (specify):</li> </ul>	
	escription of Rep		
To repair GI pipe line	3 IN THE FACULTY	ROOM. NO ELE	ECTRICAL CURRENT
Materials/Supplies/Parts:	☐ Available		☐ Not Available
Filled in by PPO personnel			
Part/Supplies/Materials Required	Manpower F	Requirement	Estimated hours/days to finished
Inspected by:  PPO Maintenance	Checked & Verified by:		Approved by:  PPO Director
	1	PPO Unit Head	LLO Director

Vision: Mission: