

OFFICE PERFORMANCE COMMITMENT & REVIEW FORM (OPCR)

I, MARLON G. BURLAS Head of the WATER AND SEWERAGE SYSTEM MAINTENANCE UNIT commits to deliver and agree to be rated on the attainment of the following targets in accordance with the indicated measures for the period: January to June 2017

MARLON G. BURLAS

Ratee

Noted:

MARIO LIMO VALENZONA

Director, GSD

Approved:

EDGARDO E. TULIN
President

Personnel Composition	Position Title/Designation	Number	
Head	Unit Head	1	
Regular staff	Adm. Aide V	1	
Casual Staff	Plumber Foreman	1	
Sub-TOTAL		3	
Job Order	Plumber Welder	1	Rating Equivalents:
	Pump Operator	2	5 - Outstanding
	Plumber	2	4 - Very Satisfactory
	Laborers	4	3 - Satisfactory
Sub Total		9	2 - Fair
TOTAL		12	1 - Poor


UMFO6- General Administration Support Services
OVPAF-MFO4, Physical Facilities Development and Maintenance
GSD, MFO4, Water and Sewerage Maintenance

MFOs/PAPS	Success Indicators	Persons Responsible	Target	Actual Accomplishment	% as of June 30	Rating				Remarks
						Q ¹	E ²	T ³	A ⁴	
WSSMU-MFO1- Water Distribution System for new and major repairs/renovations	PI 1.1 No. of Water distribution system in new and renovated/implemented Academic and Research Buildings	M. BURLAS, G. ARPOCEPLE and A. Singson 9 Job Orders	4	6	66.67%	5	5	5	5	
	PI 1.2 No. of of Water distribution system in new and renovated/implemented Administrative Buildings		1	2	50.00%	5	5	4	4.66667	
	PI 1.3 No. of Water distribution system in new and renovated/implemented IGP Building and structures		1	2	50.00%	5	5	4	4.66667	
	PI 1.4 No. of Water distribution system in new and renovated/implemented Student/ staff housing units		1	3	33.33%	5	5	4	4.66667	
	PI 2. 1 No. of plumbing systems improvements/repairs inside Academic and research buildings		50	90	55.56%	5	5	4	4.66667	

WSSMU-MFO2- Plumbing System improvement and maintenance inside Buildings	PI-2.2 No. of Plumbing system improvements/repairs inside Administrative Buildings	10	85	11.76%	5	5	4	4.66667	
	PI-2.3 No. of Plumbing system improvements/repairs inside IGP Buildings and structures	10	55	18.18%	5	5	4	4.66667	
	No. of Plumbing system improvements/repairs inside Student/Staff Housing units	40	55	72.73%	5	5	5	5	
WSSMU,MFO3- Water Distribution System repair and maintenance outside	PI 3.1 No. of Water Distribution Lines repaired/maintained	15	25	60.00%	5	5	4	4.66667	
Total Over all Rating								42.6667	
Average Rating								4.74074	

by: _____

Calibrated by:



REMBERTO A. PATINDOL


Planning Office

Date: _____

PMT

Date: _____

Recommending Approval:




REMBERTO A. PATINDOL

Vice President

Date: _____

Approved by:



EDGARDO E. TULIN

President

Date: _____

1 - Quality

2- Efficiency

3 - Timeliness

4 - Average